

Product Safety Recall



MASTERCRAFT A/S IV WHITE WALL TYRES WITH SIZES P235/75R15 AND P205/75R15 MANUFACTURED BETWEEN 8 TO 18 FEBRUARY 2017

Identification: The affected Mastercraft A/S IV white wall tyres were manufactured between 8 February 2017 and 18 February 2017, and supplied in Australia between 1 March 2017 and 31 December 2017. Each tyre is marked with a DOT Identification Number.

Product Line/Brand Name	Size	DOT Identification Number
Mastercraft A/S IV	P235/75R15	R7 HL FEB 0617 or 0717
Mastercraft A/S IV	P205/75R15	R7 UL FEB 0617 or 0717

To determine if your tyre is subject to this recall, please:

1. Find the tyre's DOT Identification Number which is located on the lower sidewall of the tyre.
2. The DOT sequence begins with the code **R7HLFEB** or **R7ULFEB**. The last 4 digits of the DOT Identification Number is a date code which comprises of a 2-digit code for the week and a 2-digit code for the year of manufacture of the tyre. If your tyre's date code is either **0617** or **0717** your tyre is subject to this recall.

The following example depicts a DOT serial number ending with 0617.



Defect: Affected tyres were manufactured with an incorrect rubber compound on the belt wire which may result in poor adhesion of the rubber to the belt wires.

Hazard: The affected tyres may develop an in-service audible noise, unsatisfactory ride condition, belt separation, or distortion in the tread area that if undetected may ultimately result in a tyre failure leading to the loss of vehicle control and increase the risk of a possible crash.

What to do: If you believe you have an affected tyre, please immediately contact Exclusive Tyres to arrange for identification and replacement of any affected tyres free of charge.

Contact: For further information please go to www.mastercrafttires.com.au or call 1800 681 298.

See www.recalls.gov.au for
Australian Product Recall Information